



## Supplementary Material





Figure 1. Integrated natural disaster risk in facilities at (a) El Quisco and (b) San Antonio.



**Figure 2.** (a) Degree of hazard, (b) Vulnerability and (c) Risk evaluation in a highly exposed to tsunami events sector at San Antonio.